9th November 1961]

Serial number and name of factory producing Agricultural implements.	*Type of implements produced.*
(1)	(2)
15 Kumbakonam Co-operative Metal Works; Limited, Kumbakonam—*cont.*	6 Inter-cultivators improved 3 inches.
	Do. 5 ,,
	Do. 4 ,,
	Do. 6 ,,
	7, 8, 9 and 10 are made to order at special rates.
	7 Seed treating drum
	8 Fire bucket 12 inches size.
	9 Buckscraper small size.
	10 Puddler wet land 2 feet.
	Do. 3 ,,
	11 Ploughs, Melur type complete.
	12 Iron ploughs 'Commet' No. 1 (BSG type without handle).
	Iron ploughs 'Commet' No. 1 (BSG type with handle).
	Iron ploughs 'Commet' No. 2 (without handle).
	Iron ploughs 'Commet' No. 2 (with handle).
	12 Wheel-barrows (two wheels).
	14 Levelling boards (72″ × 12″ × 1½″).
	15 Bund-former.
	16 Crow-bar 2′ × ⅞″.
	Do. 6′ × 1⅛″.
16 Government Service Centre for Brassware and Cutlery Industry, Kumbakonam.	Hutsuta type dusters and Rocker type sprayer.

APPENDIX V.

[Vide answer to starred question No. 1936, asked by Srimathi Hemalatha Devi at the meeting of the Legislative Assembly held on 9th November 1961 page 20 supra.]

A.—(*a*) No separate provision is made for each district. The expenditure is incurred out of the lump-sum provision made in the Budget for 'Special Minor Irrigation Programme' for the State as a whole. The amount spent during the Second Five-Year Plan period in Salem district is Rs. 19·81 lakhs.

(*b*) *The following works were completed in Dharmapuri taluk of Salem district up to the end of 31st March* 1961 :—

1 Special repairs to Settikarai tank and supply channel.
2 Do. Kodampatti Chinna Eri.
3 Do. Guddalahalli tank.
4 Do. Rajapalayam (or) Pudu Eri.
5 Do Singalleri tank.
6 Do. Sugganahalli anicut.
7 Do. Rajapalayam anicut and supply channel.
8 Do. Boodahalli tank.
9 Do. Papparapatti Chinneri.

[9th November 1961

10 Special repairs to Jaidalam tank.
11 Do. Papparapatty Big tank.
12 Do. Tala Eri and Anai.
13 Do. Gollahalli tank.
14 Do. Chikkarandhalli tank and Sudugadu anai supply channel.
15 Do. Elumichanhalli tank.
16 Do. Marvadi tank.
17 Do. Muthur Peria Eri.
18 Do. Vanian anicut and supply channel.
19 Do. Keelanchiamman tank.
20 Do. Sivadi Peria Eri.
21 Do. Pidaman Eri.
22 Do. Mathan Eri.
23 Do. Sivadi Chinna Eri.
24 Do. Narainahalli tank.
25 Do. Sikkathimmanahalli tank.
26 Do. Appasamudram tank.
27 Do. Nimmanagiri tank.
28 Do. Bandarahalli tank.

(c) *List of works programmed for* 1961–62 *in respect of Dharmapuri taluk of Salem district under the control of Chief Engineer (Irrigation).*

1 Forming a tank across Maravathipallam near Sunchalanatham village.

2 Forming a reservoir across Maddalapallam near Donnakuttahalli.

3 Forming a tank near Umayampatti village.

4 Forming a tank near Mulabellur in Sanchalanatham village.

5 Forming a tank across Periapallam in Perumbalai village.

6 Restoring the old breached Pallipatti tank.

List of works programmed for 1961–62 *in respect of Dharmapuri taluk of Salem district under the control of Superintending Engineer (Food Production).*

1 Special repairs to Mangarai Eri.
2 Do. Kottai Eri (Kotteri tank).
3 Do. Anakalur Eri.
4 Do. Laligam.
5 Do. Punnathanhalli tank.
6 Do. Vellaigoundenkuttai.

Note.—If the schemes are found feasible after investigation they will be consideredfor sanction and execution.